

Potentiometer + Geared limit switches
 Potentiometer + Getriebeendschalter

Serie DW 60

Massbild / Outline drawing

$\varnothing d = 9\text{-h}8$

$s = 8,5$

$F = \Rightarrow 40\text{ N} \quad \Downarrow 80\text{ N}$

MS = Montagefläche / Mounting surface

