



**Skales**

Order code	Picture	Description	Comments
5940.17.800		Standard - Scale SK 360	0-360°
5940.17.900		Standard - Scale SK 360	360-0° (CCW)
5940.18.800		Standard - Scale SK 100	0-330° = 0-100%
5940.18.300		Standard - Scale SK 100	0-270° = 0-100%
5940.18.000		Standard - Scale SK 270	0-270°
5940.22.300		Standard - Scale SK	Arrow

**Skales**

Order code	Picture	Description	Comments
5940.19.300	 A circular stainless steel scale with a central brass hub. The scale has six graduation marks around the perimeter, labeled 1 through 6.	Special - Scale SK 6	0-6°
5940.19.700	 A circular stainless steel scale with a central brass hub. The scale has ten graduation marks around the perimeter, labeled 1 through 10.	Special - Scale SK 10	0-10°
5940.20.500	 A circular stainless steel scale with a central brass hub. The scale has eighteen graduation marks around the perimeter, labeled 1 through 18.	Special - Scale SK 18	0-18°
5940.21.500	 A circular stainless steel scale with a central brass hub. The scale has forty-eight graduation marks around the perimeter, labeled 1 through 48.	Special - Scale SK 48	0-48°