

MR 310

Schema / Diagram

J1 WAGO PN: 733-112 (12 PIN TERMINAL)	
1	A+
2	A-
3	GND
4	B+
5	B-
6	GND
7	A oc
8	B oc
9	GND
10	+Vs
11	not used
12	shield

J2 WAGO PN: 733-110 (10 PIN TERMINAL)	
1	Div A+
2	Div A-
3	GND
4	Div B+
5	Div B-
6	GND
7	GND
8	±10V Out
9	GND
10	4-20mA Out

J3 WAGO PN: 733-106 (6 PIN TERMINAL)	
1	GND
2	+5V Out
3	TX+ →
4	TX- →
5	RCV+ ←
6	RCV- ←